

FIG.1




FIG.2




FIG.3




FIG.4




FIG.5




FIG.6




FIG.7




FIG.11




FIG.8




FIG.9




FIG.10




FIG.12




FIG.13




FIG.14

5A

WHICH DO YOU WANT TO PERFORM?

1. COMPARATIVE MEASUREMENT
2. STEREOSCOPIC MEASUREMENT

FIG.15

5B

WHICH DO YOU WANT TO USE?

1. DIRECT-VISION ADAPTER
2. SIDE-VISION ADAPTER

FIG.16




FIG.17




FIG.18A




FIG.18B




FIG.19




FIG.20A




FIG.20B




FIG.21




FIG.22A




FIG.22B




FIG.23A




FIG.23B




FIG.24A




FIG.24B




FIG.26A




FIG.26B




FIG.27A




FIG.27B




FIG.25




FIG.28




FIG.29A




FIG.29B




FIG.31A




FIG.31B




FIG.30




FIG.32




FIG.33




FIG.34

